## Antlers at Vail Capital Project & Reserve Study Summary - Aug 2019

| Component                | Action      | Useful<br>Life | Remaining<br>as of<br>07/17' | Comments                              | Est. Cost<br>Total cost | Complete  | In<br>Progress | Estimate<br>19-20 | Est Cost<br>20-21 | Replace<br>As needed | No need to<br>address |
|--------------------------|-------------|----------------|------------------------------|---------------------------------------|-------------------------|-----------|----------------|-------------------|-------------------|----------------------|-----------------------|
| Security System          | Modernize   | 10             | 0                            | Complete                              | \$23,300                | \$23,300  |                |                   |                   |                      |                       |
| Commercial Dryers        | Replace     | 15             | 0                            | Complete                              | \$15,000                | \$15,000  |                |                   |                   |                      |                       |
| Patio Furniture          | Replace     | 10             | 0                            | Complete                              | \$14,750                | \$14,750  |                |                   |                   |                      |                       |
| Pool Cover               | Replace     | 8              | 0                            | Complete                              | \$9,500                 | \$9,500   |                |                   |                   |                      |                       |
| Guest Launry             | Replace     | -              | 0                            | Complete                              | \$15,600                | \$15,600  |                |                   |                   |                      |                       |
| Lobby/Offices            | Remodel     | 0              | 0                            | In progress, Antlers 2020 Project     | \$4,300,000             |           | \$4,300,000    |                   |                   |                      |                       |
| Wood Exteriors           | Stain/Paint | 3              | 2                            | In progress, Antlers 2020 Project     | \$12,000                |           | \$12,000       |                   |                   |                      |                       |
| Board Room               | Remodel     | 20             | 3                            | In progress, Antlers 2020 Project     | \$400,000               |           | \$400,000      |                   |                   |                      |                       |
| Lennox/Mtsbshi Condenser | Replace     | 20             | 3                            | In progress, Antlers 2020 Project     | \$26,000                |           | \$26,000       |                   |                   |                      |                       |
| Computer/IT Equipment    | Replace     | 4              | 1                            | In progress                           | \$31,750                |           | \$31,750       |                   |                   |                      |                       |
| Balcony Rails            | Paint       | 5              | 0                            | Schedule Fall 2019                    | \$28,050                |           |                | \$28,050          |                   |                      |                       |
| Spas                     | Resurface   | 6              | 0                            | Schedule Fall 2019                    | \$20,000                |           |                | \$20,000          |                   |                      |                       |
| Roof                     | Replace     | 0              | 0                            | Schedule Fall 2019                    | \$11,500                |           |                | \$11,500          |                   |                      |                       |
| Outdoor Carpeting        | Replace     | 7              | 0                            | 50% Spring of 20' and 50% fall of 20' | \$50,000                |           |                | \$25,000          | \$25,000          |                      |                       |
| Walkway Deck             | Recoat      | 15             | 0                            | 50% Spring of 20' and 50% fall of 20' | \$65,000                |           |                | \$32,500          | \$32,500          |                      |                       |
| Walkway Deck Railing     | Paint       | 5              | 0                            | 50% Spring of 20' and 50% fall of 20' | \$37,000                |           |                | \$18,500          | \$18,500          |                      |                       |
| Pool                     | Resurface   | 12             | 1                            | Schedule Fall 2020                    | \$80,000                |           |                |                   | \$80,000          |                      |                       |
| Card/Fob Reader System   | Replace     | 15             | 0                            | Schedule Spring 2021                  | \$53,900                |           |                |                   | \$53,900          |                      |                       |
| Kitchen Appliances       | Replace     | 10             | 0                            | Replace as needed                     | \$56,000                |           |                |                   |                   | \$56,000             |                       |
| Stucco/EIFS              | Seal/Paint  | 15             | 0                            | Touch up as needed                    | \$476,550               |           |                |                   |                   | \$476,550            |                       |
| Exhaust Fan System       | Replace     | 0              | 0                            | No need to address at the moment      | \$50,000                |           |                |                   |                   |                      | \$50,000              |
| CO Monitors              | Replace     | 10             | 0                            | No need to address at the moment      | \$14,500                |           |                |                   |                   |                      | \$14,500              |
| Sauna Changing Room      | Refurbish   | 20             | 3                            | No need to address at the moment      | \$10,000                |           |                |                   |                   |                      | \$10,000              |
| Estimated Total          |             |                |                              |                                       | \$ 5,800,400            | \$ 78,150 | \$ 4,769,750   | \$ 135,550        | \$ 209,900        | \$ 532,550           | \$74,500              |